

Message Text

UNCLASSIFIED

PAGE 01 KINSHA 07081 271555Z POSS DUPE
ACTION EB-08

INFO OCT-01 AF-10 ISO-00 XMB-04 ERDA-07 AID-05 CEA-01
CIAE-00 COME-00 DODE-00 FEAE-00 FPC-01 H-02
INR-07 L-03 NSAE-00 NSC-05 OMB-01 PM-05 USIA-15
OES-07 SP-02 SS-15 STR-04 TRSE-00 ACDA-10 /113 W
-----097921 271842Z /53

P R 271530Z JUL 77
FM AMEMBASSY KINSHASA
TO SECSTATE WASHDC PRIORITY 4850
DEPT OF INTERIOR WASHDC

UNCLAS KINSHASA 7081

DEPT PASS EXIM

INTERIOR FOR BUREC

E.O. 11652: N/A
TAGS: ENRG, CG
SUBJECT: POSSIBLE CONSEQUENCES OF SUSPENSION OF WORK ON INGA-SHABA
TRANSMISSION LINE

1. FOLLOWING MEMO EXPRESSES OPINION OF LOCAL REPS OF BUREC
CONCERNING TECHNICAL EFFECTS OF A SUSPENSION OF WORK AND STORAGE OF
MATERIALS FOR THE INGA-SHABA TRANSMISSION LINE.

BEGIN QUOTE

2. AS REQUESTED BY THE AMERICAN EMBASSY HERE, THE BUREAU OF
RECLAMATION HEREIN IS EXPRESSING AN OPINION ON THE EFFECTS OF
A SHUTDOWN AND THE STORAGE OF INGA-SHABA MATERIALS, SUPPLIES
AND ELECTRICAL EQUIPMENT FOR A LONG PERIOD OF TIME. THE
OPINION EXPRESSED IS THE MOST EXPERT WE CAN MAKE WITH THE BACK-
GROUND AND EXPERIENCE AVAILABLE IN OUR TEAM OF TECHNICAL
ADVISORS HERE, AND IT ATTEMPTS TO EVALUATE FAIRLY ALL OF THE
LOCAL ADVERSE CONDITIONS WITH WHICH WE ARE INTIMATELY FAMILIAR.
WE HAVE BEEN REQUESTED TO PRESENT THIS IN LAYMAN'S TERMS, AND
UNCLASSIFIED

UNCLASSIFIED

PAGE 02 KINSHA 07081 271555Z POSS DUPE

WILL DO SO. WE ARE WILLING TO BE MORE DETAILED OR SPECIFIC
OR TECHNICAL, IF DESIRED.

3. AT THIS TIME THE INGA-SHABA PROJECT IN ZAIRE HAS MANY
MILLIONS OF DOLLARS INVESTED IN ELECTRICAL EQUIPMENT WHICH WILL
BE SUBJECT TO DETERIORATION AND POSSIBLE LOSS IF STORED IN-
CORRECTLY FOR A TIME PERIOD OF TWO TO FIVE YEARS. MORE EQUIP-

MENT OF THIS NATURE IS ALSO STILL ENROUTE TO ZAIRE OR IN WAREHOUSE FACILITIES IN SWEDEN. NEARLY ALL OF THIS MATERIAL ARRIVES IN ZAIRE AS SEPARATE COMPONENT PARTS AND UNTIL THESE ARE SECURELY SUPPORTED BY CONCRETE PADS OR INSTALLED IN THE CONTROLLED ATMOSPHERE STRUCTURES, ASSEMBLED AND IN MANY CASES FILLED WITH SPECIALLY PROCESSED ELECTRICAL INSULATING OIL, THE RISK OF DAMAGE FROM INTERNAL RUSTING OR MOIST AIR BEING ABSORBED BY SENSITIVE ELECTRICAL INSULATION IS GREAT. WEATHERING OF THE NORMALLY EXPOSED PAINTED SURFACES IS NOT CONSIDERED A PROBLEM.

4. OTHER ITEMS, IN PARTICULAR PORTIONS OF THE TELECOMMUNICATIONS, CONTROL AND PROTECTION SYSTEMS, HAVE INTERNAL COMPONENTS WHICH HAVE SHELF LIFE CHARACTER AND TIME ALONE WILL PRODUCE A NEED FOR MAINTENANCE BEFORE THESE MAY BE PLACED IN SERVICE. IN THIS MANNER THEY RESEMBLE A COLOR TELEVISION SET BOTH IN CHARACTERISTICS AND INTERNAL COMPONENTS. FURTHER, THESE ITEMS ARE DESIGNED AND CONSTRUCTED FOR USE IN A ROOM WHERE HEAT, COLD AND DUST ARE CONTROLLED TO ASSURE A NORMAL LIFE SPAN.

5. ALL THE AFOREMENTIONED DEVICES WERE PREPARED FOR SHIPMENT BY THE MANUFACTURERS AND ARRIVED IN ZAIRE WITH A PROTECTIVE DRY AIR BLANKET, UNDER VACUUM OR WITH OTHER SHORT-TIME PROTECTIONS. THE LIFE OF THESE PROTECTIONS IS NOW BEING EXCEEDED IN SOME INSTANCES. AT THE RECOMMENDATION OF THE MANUFACTURERS AND IN SOME CASES AIDED BY HIS REPRESENTATIVE, THE MATERIALS ARE BEING UNCLASSIFIED

UNCLASSIFIED

PAGE 03 KINSHA 07081 271555Z POSS DUPE

INSPECTED AND AS POSSIBLE THE SHORT-TIME PROTECTIONS RECONDITIONED. THIS IS NOT AN ADEQUATE PREPARATION FOR LONG-TERM STORAGE.

6. LONG-TERM STORAGE WILL DEMAND THE PROTECTION OF OIL-FILLED DEVICES. THIS IS DIFFICULT TO ACHIEVE UNDER PRESENT CIRCUMSTANCES DUE TO THEIR WEIGHT WHEN FILLED WITH OIL.

7. NOT ONLY IS THE ELECTRICAL EQUIPMENT ENDANGERED BUT THE TRANSMISSION LINE IS ALSO. THE LINE IS 1700 KILOMETERS LONG THROUGH UNDEVELOPED AND IMPASSABLE AREAS, EXCEPT FOR THE CAMPS AND ACCESS AS DEVELOPED FOR THE PROJECT. WITHOUT MAINTENANCE THE ROADS WILL WASH OUT, MAKING THE AREAS INACCESSIBLE; AND WITHOUT CLEAN UP AROUND THE CAMPS AND MATERIALS YARDS, WE STAND A VERY GOOD CHANCE OF LOSING MUCH OF IT TO GRASS FIRES OR THE ELEMENTS.

8. EQUIPMENT DETERIORATION: PARKED EQUIPMENT WOULD LOSE TIRES, BATTERIES, UPHOLSTERY, ETC. AS WELL AS RUST THROUGH THE BODIES IN A SHORT TIME BECAUSE OF TROPICAL CONDITIONS.

9. CONSTRUCTION FORM WORK (FOR PLACEMENT OF CONCRETE) IS

ALREADY DETERIORATING TO THE POINT WHERE IT WILL BE NECESSARY
TO REWORK IT BEFORE IT CAN BE USED. A FEW MORE MONTHS AND IT WILL
REQUIRE REPLACEMENT.

10. MILLIONS OF DOLLARS WORTH OF ELECTRICAL EQUIPMENT COULD BE
LOST IN PROLONGED STORAGE BECAUSE OF CORROSION, MOISTURE SEEPING
INTO THE ELECTRICAL INSULATION, RUST, AND MANY OTHER CAUSES.
THIS EQUIPMENT IS DESIGNED TO OPERATE AND NOT TO BE STORED.
WHEN OPERATING, IT IS HOT ENOUGH TO KEEP DRY. WHEN IT IS
NOT OPERATING, IN THIS TROPICAL CLIMATE IT IS ALMOST IMPOSSIBLE
TO KEEP DRY, AND MOISTURE CAN RUIN IT VERY QUICKLY.

11. IN OUR OPINION ANY SHUTDOWN OF THE JOB WOULD BE DELETERIOUS
TO THE PROJECT. WE RECOMMEND AS STRONGLY AS POSSIBLE ON
UNCLASSIFIED

UNCLASSIFIED

PAGE 04 KINSHA 07081 271555Z POSS DUPE

TECHNICAL GROUNDS, THAT THE PROJECT BE CONTINUED IMMEDIATELY.
THERE IS A GOOD POSSIBILITY THAT EXTENSIVE EQUIPMENT DAMAGE
COULD RESULT WITH A PROLONGED SHUTDOWN. END QUOTE.
CUTLER

UNCLASSIFIED

NNN

Message Attributes

Automatic Decaptioning: X
Capture Date: 01-Jan-1994 12:00:00 am
Channel Indicators: n/a
Current Classification: UNCLASSIFIED
Concepts: PROGRAMS (PROJECTS), POWER TRANSMISSION LINES
Control Number: n/a
Copy: SINGLE
Sent Date: 27-Jul-1977 12:00:00 am
Decaption Date: 01-Jan-1960 12:00:00 am
Decaption Note:
Disposition Action: n/a
Disposition Approved on Date:
Disposition Case Number: n/a
Disposition Comment:
Disposition Date: 01-Jan-1960 12:00:00 am
Disposition Event:
Disposition History: n/a
Disposition Reason:
Disposition Remarks:
Document Number: 1977KINSHA07081
Document Source: CORE
Document Unique ID: 00
Drafter: n/a
Enclosure: n/a
Executive Order: N/A
Errors: N/A
Expiration:
Film Number: D770269-0350
Format: TEL
From: KINSHASA
Handling Restrictions: n/a
Image Path:
ISecure: 1
Legacy Key: link1977/newtext/t19770715/aaaaamgj.tel
Line Count: 140
Litigation Code IDs:
Litigation Codes:
Litigation History:
Locator: TEXT ON-LINE, ON MICROFILM
Message ID: 83008663-c288-dd11-92da-001cc4696bcc
Office: ACTION EB
Original Classification: UNCLASSIFIED
Original Handling Restrictions: n/a
Original Previous Classification: n/a
Original Previous Handling Restrictions: n/a
Page Count: 3
Previous Channel Indicators: n/a
Previous Classification: n/a
Previous Handling Restrictions: n/a
Reference: n/a
Retention: 0
Review Action: RELEASED, APPROVED
Review Content Flags:
Review Date: 12-Jan-2005 12:00:00 am
Review Event:
Review Exemptions: n/a
Review Media Identifier:
Review Release Date: n/a
Review Release Event: n/a
Review Transfer Date:
Review Withdrawn Fields: n/a
SAS ID: 1736917
Secure: OPEN
Status: NATIVE
Subject: POSSIBLE CONSEQUENCES OF SUSPENSION OF WORK ON INGA-SHABA TRANSMISSION LINE
TAGS: ENRG, EINV, CG, INGA SHABA
To: STATE INT
Type: TE
vdkgvwkey: odb://SAS/SAS.dbo.SAS_Docs/83008663-c288-dd11-92da-001cc4696bcc
Review Markings:
Margaret P. Grafeld
Declassified/Released
US Department of State
EO Systematic Review
22 May 2009
Markings: Margaret P. Grafeld Declassified/Released US Department of State EO Systematic Review 22 May 2009